

VEHICLE INSPECTION REPORT

PE63NBL

Daf LF 45.140

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 05/11/2013

VIN XLRAE45FF0L432269

Gearbox MANUAL

Year 2013

Body Style Box Van

Axle Combi 4x2

Mileage 1,154,550 Km
Warranted

Service history Yes

Rear Suspension Steel

Service documents Printout

Tail Lift Cantilever

Fuel Type DIESEL

MOT Due 30/11/2026

GVW 7500kg

Cab Type DAY CAB

Colour RED

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3


OSO4

Features


- Cruise control
- Radio/CD
- Front electric windows
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Poor Previous Repair
Poor Paint



2: Bumper Front
Dented
With Paint Damage



3: Wing nsf
Scratched
Over 25mm Thru Paint

4: Door osf
Scratched
Over 25mm Thru Paint



5: Door Pad osf
Soiled
Heavy

6: Carpets Front
Holed
Over 3mm



7: Seat Base Cover nsf
Holed
Over 3mm

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		