

VEHICLE INSPECTION REPORT

PE63NDK

Daf LF 45.140

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 25/10/2013

Year 2013

Mileage 862,049 Km Warranted

Fuel Type DIESEL

GVW 7500kg

Colour RED

VIN XLRAE45FF0L431825

Body Style Box Van

Service history Yes

MOT Due 30/06/2027

Cab Type DAY CAB

Gearbox MANUAL

Axle Combi 4x2

Rear Suspension Steel

Tail Lift Cantilever

WARNING LIGHT ON DASH

Tyres


NSF NSI1 NSI2 NSI3 NSI4




OSF OSI1 OSI2 OSI3 OSI4

Spare NSO1 NSO2 NSO3 NSO4


OSO1 OSO2 OSO3 OSO4

Photos





Condition Check



Damage Photos



1: Wing of
Scratched
Over 25mm Thru Paint



2: Bonnet
Chipped
Multiple Chips



3: Screen Front
Chipped
Over 10mm

4: Bumper Front
Scratched
Over 25mm Not Thru Paint



5: Wing nsf
Chipped
Multiple Chips

6: Door Mirror Assy nsf
Broken
Replace



7: Door nsf
Scratched
Over 25mm Not Thru Paint

8: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



9: Qtr Panel osr
 Scratched
 Over 25mm Not Thru Paint

10: Door osf
 Chipped
 Edge Chip



11: Wing Front Arch Extension os
 Scuffed (Unpainted)
 Over 100mm

12: Centre Console Front
 Broken
 Replace

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		-	
Engine Runs	OK			Gearbox 1st and Reverse Test	OK		
Brakes	OK			Clutch Slip Test from Static	OK		
Parking Brake	OK			Gearbox Static Gear Selection (engine running)	OK		
				No Excessive Smoking	OK		
EML light illuminated	OK			Oil warning light illuminated	OK		
Airbag light illuminated	OK			DPF light illuminated	Fault		
ABS light illuminated	OK			Service indicator light illuminated	OK		