

VEHICLE INSPECTION REPORT

PE65VDF

Daf LF 150

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 29/10/2015

Colour RED

Cab Type DAY CAB

Year 2015

VIN XLRAEL1500L448518

Gearbox MANUAL

Mileage 975,061 Km Warranted

Body Style Box Van

Axle Combi 4x2

Fuel Type DIESEL

Service history Yes

Rear Suspension Steel

GVW 7500kg

MOT Due 30/11/2026

Tail Lift Cantilever

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4


OSO1





OSO2

OSO3


OSO4

Photos





Condition Check



Damage Photos



1: Wing osf
Poor Previous Repair
Poor Paint

2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Chipped
Multiple Chips



4: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



5: Bumper Front
Dented
With Paint Damage



6: Wing Front Arch Extension ns
Scuffed (Unpainted)
UpTo 100mm



7: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



8: Bumper Rear
Rusted
Over 5mm



9: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

10: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



11: Door osf
Dented
With Paint Damage

12: Fog Lamp Surround ns
Broken
Replace



13: Grille Front
Broken
Replace

14: Wing Front Arch Extension os
Scuffed (Unpainted)
UpTo 100mm



15: Seat Base Cover nsf
 Holed
 Over 3mm

Interior

Carpet Condition		Upholstery Condition	
Seat Condition	Average Average	Odour	Average -
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK