

VEHICLE INSPECTION REPORT

EX22ZXB

Ford Transit 350 2.0 EcoBlue 130ps

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 07/03/2022

Year 2022

Mileage 65,537 Miles Not Warranted

Fuel Type DIESEL

GVW 3500kg

Colour WHITE

VIN WF0EXXTTREM31075

Body Style Panel Van L3

MOT Due 06/03/2027

CAP Clean £9,350.00

CAP Average £8,500.00

CAP Below £7,150.00

Gearbox MANUAL

Gears 6

WARNING LIGHTS ON DASH, AD BLUE, SIDE LOAD DOOR

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Bluetooth connection
- Front electric windows
- Park assist camera
- Drivers airbag
- Digital radio
- Central locking
- USB/iPod interface
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front Grill
Broken
Replace



3: Bumper Front
Scratched
Over 100mm Thru Paint

4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Wing nsf
Dented
Over 30mm

6: Wing Front Arch Extension ns
Broken
Replace




7: Door Mirror Assy nsf
Broken
Replace

8: Wing nsf
Dented
With Paint Damage



9: Door nsf
Scratched
Over 25mm Thru Paint

10: Door nsf
Scratched
Over 25mm Thru Paint



11: Roof
Scratched
Over 25mm Thru Paint

12: Qtr Panel nsr
Cracked
Replace



13: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

14: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



15: Qtr Panel nsr
Cracked
Replace

16: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



17: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

18: Qtr Panel nsr
Dented
Over 30mm



19: Bumper Rear
Insecure
Action Required

20: Door osr
Scratched
Over 25mm Thru Paint



21: Door osr
Scratched
Over 25mm Thru Paint

22: Qtr Panel osr
Scratched
Over 25mm Thru Paint



23: Qtr Panel osr
Scratched
Over 25mm Thru Paint

24: Qtr Panel osr
Scratched
Over 25mm Thru Paint



25: Qtr Panel osr
Scratched
Over 25mm Thru Paint

26: Qtr Panel osr
Scratched
Over 25mm Thru Paint



27: Qtr Panel osr
Scratched
Over 25mm Thru Paint

28: Qtr Panel Moulding os
Scratched (Painted)
Over 25mm Thru Paint



29: Qtr Panel Moulding os
Scratched (Painted)
Over 25mm Thru Paint

30: Roof
Scratched
Over 25mm Thru Paint



31: Door osf
Scratched
Over 25mm Thru Paint

32: Door Mirror Assy osf
Broken
Replace



33: Wing osf
Dented
Over 30mm

34: Wing Front Arch Extension os
Broken
Replace



35: Bumper Front
Scratched
Over 100mm Thru Paint

36: Wing osf
Scratched
Over 25mm Not Thru Paint



37: Seat Base Cover osf
Holed
Over 3mm

38: Dash Warning Lights
Displayed
No Action



39: Fascia Trim
Damaged
Replace

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Poor	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Gearbox Static Gear Selection (engine running)	OK	
Parking Brake	OK		No Excessive Smoking	OK	
EML light illuminated	OK		DPF light illuminated	OK	
Airbag light illuminated	Fault				
ABS light illuminated	Fault				