

VEHICLE INSPECTION REPORT

KM11NKU

Mercedes-Benz Sprinter 313 CDI

Non Runner
Inspection

Serious Damage?		Vehicle	
No		VAT	Plus VAT
		V5	Present

Details

Location	Avonmouth	GVW	3500kg	CAP Clean	£1,000.00
Reg. date	01/06/2011	Colour	WHITE	CAP Average	£760.00
Year	2011	VIN	WDB9066332S545686	CAP Below	£570.00
Mileage	Not Showing	Body Style	Panel Van LWB	Gearbox	MANUAL
Fuel Type	DIESEL	MOT Due	Expired	Gears	6

NON-RUNNER-ENGINE REMOVED, NO GEARBOX, COMES WITH NEW & OLD ENGINE, MOT SHOWS 258,880 MILES 29/05/2025

Tyres

NSF

NSR

OSF


OSR



Spare

Features


- Bluetooth connection
- Radio/CD
- Front electric windows
- Drivers airbag
- Cloth seat trim

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Wing nsf
Cracked
Replace



3: Bumper Front
Insecure
Action Required

4: Door Mirror Assy nsf
Broken
Replace



5: Sill ns
Rusted
Over 5mm

6: Qtr Panel nsr
Chipped
Multiple Chips



7: Qtr Panel nsr
Dented
With Paint Damage

8: Sill ns
Dented
Over 30mm



9: Qtr Panel nsr
Cracked
Replace

10: Qtr Panel nsr
Poor Previous Repair
Paint Flake



11: Lamp nsr
Broken
Replace

12: Qtr Panel Moulding ns
Missing
Replace



13: Door osr
Dented
Over 30mm

14: Door osr
Dented
Over 30mm




15: Qtr Panel Moulding os
Missing
Replace

16: Bumper Rear
Scratched
Over 100mm Thru Paint



17: Qtr Panel osr
Rusted
Over 5mm

18: Qtr Panel osr
Rusted
UpTo 5mm



19: Sill os
Dented
Over 30mm

20: Qtr Panel osr
Rusted
Over 5mm



21: Bumper Front
Insecure
Action Required

22: Carpets Front
Missing
Replace



23: Fascia Trim
Missing
Replace

Interior

Carpet Condition
Seat Condition

Poor
Average

Upholstery Condition
Odour

Average
-

Engine Runs Fault