

VEHICLE INSPECTION REPORT

SN20XUB

Daf CF 320

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 22/07/2020

Year 2020

Mileage 107,369 Km Not Warranted

Fuel Type DIESEL

GVW 26000kg

Colour WHITE/RED

VIN XLRASM4700G294560

Body Style Dropside & Crane

MOT Due 31/12/2026

Cab Type DAY CAB

Gearbox MANUAL

Axle Combi 6x2

Steering Combi Rear-Lift Steer

Rear Suspension Air

FASSI F195A.2.23 (3 EXT) REMOTE CRANE (YEAR 2019)

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4


OSO1





OSO2


OSO3

OSO4


Photos







Condition Check



Damage Photos



1: Seat Base Cover osf
Torn
Over 3mm



2: Door Moulding osf
Scuffed (Unpainted)
Over 100mm



3: Bonnet
Chipped
Multiple Chips

4: Bumper Front
Dented
With Paint Damage



5: Wing osf
Scratched
Over 25mm Thru Paint

6: Door osf
Dented
With Paint Damage



7: Qtr Panel osr
Dented
Over 30mm

8: Qtr Panel nsr
Dented
With Paint Damage



9: Door nsf
Dented
With Paint Damage

10: Door Moulding nsf
Broken
Replace

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Poor		Odour		-	
Engine Runs	OK			Gearbox 1st and Reverse Test	OK		
Brakes	OK			Clutch Slip Test from Static	OK		
Turbo Boosting	OK			Gearbox Static Gear Selection (engine running)	OK		
Parking Brake	OK			No Excessive Smoking	OK		
EML light illuminated	OK			Oil warning light illuminated	OK		
Airbag light illuminated	OK			DPF light illuminated	OK		
ABS light illuminated	OK			Service indicator light illuminated	OK		
Roof / sunroof	OK			Radio	OK		
Windows	OK			Steering	OK		