

VEHICLE INSPECTION REPORT

EK210ZG

Ford Transit 350 LEADER 2.0 ECOBLUE 130PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 09/04/2021

Year 2021

Mileage 130,350 Miles Not Warranted

Fuel Type DIESEL

GVW 3500kg

Colour WHITE

VIN WF0EXXTTREM08850

Body Style Panel Van L4

MOT Due 12/09/2026

CAP Clean £5,725.00

CAP Average £5,100.00

CAP Below £4,175.00

Gearbox MANUAL

Gears 6

WARNING LIGHT ON DASH SIDE LOADING DOOR, AD BLUE, TOW BAR

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Front parking sensor
- Rear parking sensor
- Front electric windows

Photos





Condition Check



Damage Photos



1: Wing osf
 Scratched
 Over 25mm Not Thru Paint

2: Panel Front
 Dented
 Between 10mm + 30mm



3: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

4: Bonnet
Chipped
Multiple Chips



5: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

6: Wing nsf
Scratched
Over 25mm Not Thru Paint




7: Door Mirror Assy nsf
Broken
Replace

8: Flasher Side Repeater ns
Broken
Replace



9: Door nsf
Chipped
Edge Chip

10: Door nsf
Scratched
Over 25mm Not Thru Paint



11: Door nsr
Scratched
Over 25mm Thru Paint

12: Door Moulding nsr
Scuffed (Unpainted)
Over 100mm



13: Door nsr
Dented
Between 10mm + 30mm

14: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm




15: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

16: Door osr
Dented
With Paint Damage



17: Door nsr
Dented
Over 2 UpTo 10mm

18: Door osr
Scratched
Over 25mm Thru Paint



19: Lamp nsr
Broken
Replace

20: Door nsr
Dented
Over 30mm




21: Lamp nsr
Broken
Replace

22: Lamp osr
Broken
Replace



23: Qtr Panel osr
Dented
With Paint Damage

24: Qtr Panel osr
Scratched
Over 25mm Thru Paint



25: Qtr Panel osr
Dented
Between 10mm + 30mm

26: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



27: Bumper Rear Moulding
Broken
Replace

28: Qtr Panel osf
Scratched
Over 25mm Not Thru Paint



29: Door osf
Chipped
Edge Chip

30: Door Mirror Assy osf
Broken
Replace



31: Seat Base Cover osf
Holed
Over 3mm

32: Door osf
Dented
Between 10mm + 30mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK