

VEHICLE INSPECTION REPORT

PE65VAJ

Daf LF 220

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	16/10/2015	VIN	XLRAEL3700L448420	Gearbox	AUTOMATIC
Year	2015	Body Style	Box Van	Axle Combi	4x2
Mileage	889,613 Km Warranted	Service history	Yes	Rear Suspension	Steel
Fuel Type	DIESEL	Service documents	Printout	Tail Lift	Cantilever
GVW	18000kg	MOT Due	31/08/2026		
Colour	RED	Cab Type	DAY CAB		

COLLECTED AS NON-RUNNER - CAB CORROSION, WARNING LIGHTS ON DASH


Tyres




NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Cruise control
- Central locking
- Radio/CD
- Cloth seat trim
- Air conditioning
- Front electric windows

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Panel Front
Poor Previous Repair
Rippled Up To 30%



3: Bumper Front
Dented
Over 30mm

4: Bumper Front
Scratched
Over 100mm Thru Paint



5: Wing nsf
Scratched
Over 25mm Thru Paint

6: Door osf
Scratched
Over 25mm Thru Paint



7: Door osf
Scratched
Over 25mm Thru Paint

8: Dash Warning Lights
Displayed
No Action



9: Door Pad osf
Soiled
Heavy

10: Carpets Front
Torn
Over 10mm



11: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition		Poor	Upholstery Condition		Poor
Seat Condition		Poor	Odour		-
Engine Runs		OK	No Excessive Smoking		OK
EML light illuminated		Fault	DPF light illuminated		Fault
ABS light illuminated		OK			