

VEHICLE INSPECTION REPORT

WU16PDO

Daf LF 180

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location	Doncaster	GVW	12000kg	Cab Type	CREW CAB
Reg. date	01/07/2016	Colour	WHITE	Gearbox	AUTOMATIC
Year	2016	VIN	XLRAEL1500L452504	Axle Combi	4x2
Mileage	154,064 Km Warranted	Body Style	Refuse Collector	Rear Suspension	Air
Fuel Type	DIESEL	MOT Due	30/09/2026		

ROMAQUIP BODY

Tyres






NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Radio/CD
- Cloth seat trim
- Cruise control
- Air conditioning
- Park assist camera
- Front electric windows
- Auxiliary input socket
- Central locking


Photos







Condition Check



Damage Photos



1: Door osf
Dented
With Paint Damage

2: Door Moulding osf
Missing
Replace



3: Door osf
Scratched
Over 25mm Thru Paint

4: Door Mirror Assy osf
Broken
Replace



5: Wing osf
Scratched
Over 25mm Thru Paint

6: Panel Front
Scratched
Over 25mm Thru Paint



7: Bumper Front
Dented
With Paint Damage

8: Panel Front
Scratched
Over 25mm Thru Paint



9: Bumper Front
Dented
With Paint Damage

10: Bumper Front Moulding
Missing
Replace



11: Door nsf
Dented
With Paint Damage

12: Door nsf
Dented
With Paint Damage



13: Door nsf
Dented
With Paint Damage

14: Door Pad osf
Soiled
Heavy





15: Carpets Front
Holed
Over 3mm

16: Seat Base Cover osf
Holed
Over 3mm



17: Seat Base Cover nsf
Holed
Over 3mm

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
Poor		Poor	
Poor		-	
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		