

VEHICLE INSPECTION REPORT

BX09FZR

Daf LF 45.180

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location	Doncaster	Colour	WHITE	Gearbox	MANUAL
Reg. date	24/08/2009	VIN	XLRAE45FF0L351909	Axle Combi	4x2
Year	2009	Body Style	Box Van	Rear Suspension	Steel
Mileage	218,471 Km Warranted	Service history	Yes	Tail Lift	Cantilever
Fuel Type	DIESEL	Service documents	Printout		
GVW	10000kg	Cab Type	DAY CAB		


Tyres




NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Cruise control
- Central locking
- Auxiliary input socket
- Cloth seat trim
- Digital radio
- Front electric windows


Photos







Condition Check



Damage Photos



1: Panel Front
Cracked
Replace

2: Bonnet
Scratched
Over 25mm Thru Paint



3: Bonnet
Chipped
Multiple Chips



4: Bumper Front
Dented
With Paint Damage



5: Bumper Front
Rusted
Over 5mm



6: Bumper Front Grill
Broken
Replace



7: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

8: Lamp osr
Broken
Replace



9: Qtr Panel osr
Cracked
Replace

10: B Post os
Dented
Over 30mm



11: Door osf
Dented
With Paint Damage

12: Screen Front
Cracked
Replace



13: Door Pad osf
Soiled
Heavy

14: Carpets Front
Torn
Over 10mm



15: Seat Base Cover osf
Torn
Over 3mm

16: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition		Poor	Upholstery Condition		Poor
Seat Condition		Poor	Odour		-
Engine Runs	OK		No Excessive Smoking	OK	
EML light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK				