

VEHICLE INSPECTION REPORT

BC15ZDA

Iveco Daily 70-170

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location	Doncaster	GVW	7000kg	Service documents	Printout
Reg. date	10/08/2015	Colour	WHITE	Cab Type	DAY CAB
Year	2015	VIN	ZCFC270C505039267	Gearbox	MANUAL
Mileage	133,669 Km Warranted	Body Style	Panel Van	Axle Combi	4x2
Fuel Type	DIESEL	Service history	Yes	Rear Suspension	Steel

PTO, RACKING IN REAR, MICROWAVE, WATER HEATER, HOIST, CABLE FEEDER 240V SOCKETS


Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Radio/CD
- Central locking
- Cruise control
- Front electric windows
- Cloth seat trim
- Rear parking sensor
- Drivers airbag
- Digital radio
- Passenger airbag


Photos







Condition Check



Damage Photos



1: Bumper Front
Scratched
Over 100mm Thru Paint

2: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



3: Bonnet
Chipped
Multiple Chips

4: Panel Front
Cracked
Replace



5: Wing nsf
Dented
With Paint Damage

6: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



7: Bumper Front
Scratched
Over 100mm Thru Paint

8: Door nsf
Scratched
Over 25mm Thru Paint



9: Door Moulding nsf
Scuffed (Unpainted)
Over 100mm

10: Qtr Panel nsr
Dented
With Paint Damage



11: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm

12: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



13: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm

14: Bumper Rear Moulding
Broken
Replace



15: Door nsr
Dented
With Paint Damage

16: Door nsr
Dented
Over 30mm



17: Door osf
Dented
Over 30mm

18: Wing osf
Dented
With Paint Damage



19: Seat Base Cover osf
Torn
Over 3mm

20: Carpets Front
Holed
Over 3mm



21: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	Poor	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		