

VEHICLE INSPECTION REPORT

BC15ZDD

Iveco Daily 70-170

Non Runner
Inspection

Serious Damage?	No	Vehicle	
		VAT	Plus VAT
		V5	Present

Details

Location	Avonmouth	Colour	WHITE	Cab Type	DAY CAB
Reg. date	17/08/2015	VIN	ZCFC270C305039266	Gearbox	MANUAL
Year	2015	Body Style	Panel Van	Axle Combi	4x2
Mileage	152,960 Km Warranted	Service history	Yes	Rear Suspension	Steel
Fuel Type	DIESEL	Service documents	Printout		
GVW	7000kg	MOT Due	Expired		

NON-RUNNER - HALF SHAFT REMOVED PENNY HYDRAULICS KJ150 SWING LIFT, COMPRESSOR GENERATOR, MICROWAVE, HOT WATER BOILER, RACKING IN REAR


Tyres





NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Radio/CD
- Front electric windows
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Front TowEye Cvr
Missing
Replace



3: Wing nsf
Dented
Hail - Severe

4: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



5: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

6: Qtr Panel nsr
Scratched
Over 25mm Thru Paint




7: Bumper Rear
Scratched
Over 100mm Thru Paint

8: Door nsr
Dented
With Paint Damage



9: Door osr
Dented
With Paint Damage

10: Door osr
Rusted
UpTo 5mm



11: Qtr Panel osr
Scratched
Over 25mm Thru Paint

12: Bumper Rear
Scratched
25 to 100mm Thru Paint



13: Qtr Panel osr
Rusted
Over 5mm

14: Qtr Panel osr
Scratched
Over 25mm Thru Paint



15: Door osr
Chipped
Multiple Chips

16: Door osf
Poor Previous Repair
Poor Paint



17: Carpets Front
Holed
Over 3mm

18: Fascia Trim
Damaged
Replace

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
Engine Runs	OK	Gearbox 1st and Reverse Test	Fault
Brakes	Fault	Gearbox Static Gear Selection (engine running)	Fault
Parking Brake	Fault	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		