

VEHICLE INSPECTION REPORT

BX09HCY

Daf LF 45.180

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location Doncaster

VIN XLRAE45FF0L349315

Axle Combi 4x2

Reg. date 01/03/2009

Body Style MOBILE WORKSHOP

Rear Suspension Steel

Year 2009

Service history Yes

Rear Doors Roller

Mileage 299,529 Km Warranted

Service documents Printout

Tail Lift Column

Fuel Type DIESEL

Cab Type DAY CAB

Colour WHITE

Gearbox MANUAL

COLLECTED ON LOW LOADER - TAIL LIFT SNAPPED N/S SINK, HOB

Tyres

NSF NSI1 NSI2 NSI3 NSI4

OSF OSI1 OSI2 OSI3 OSI4

Spare NSO1 NSO2 NSO3 NSO4



OSO1 OSO2 OSO3 OSO4


Features

- Cruise control
- Radio/Cassette
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front
Rusted
Over 5mm



3: Panel Front
Scratched
Over 25mm Thru Paint

4: Bumper Front Moulding
Broken
Replace



5: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

6: Qtr Panel Moulding ns
Scratched (Painted)
Over 25mm Thru Paint



7: Qtr Panel Moulding ns
Broken
Replace

8: Qtr Panel Moulding ns
Scratched (Painted)
Over 25mm Thru Paint



9: Other
N/A
N/A

10: Qtr Panel osr
Cracked
Replace



11: Door osf
Dented
With Paint Damage

12: Door osf
Scratched
Over 25mm Thru Paint



13: Door Pad osf
Soiled
Heavy

14: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		