

VEHICLE INSPECTION REPORT

YY18OKD

Daf CF 260

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location	Doncaster	GVW	18000kg	Cab Type	SPACE CAB
Reg. date	01/08/2018	Colour	BLUE	Gearbox	AUTOMATIC
Year	2018	VIN	XLRAEM3700G210863	Axle Combi	4x2
Mileage	547,621 Km Warranted	Body Style	Curtainside	Rear Suspension	Air
Fuel Type	DIESEL	MOT Due	31/10/2026	Rear Doors	Barn

Tyres




NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Cruise control
- Front electric windows
- Auxiliary input socket
- Central locking
- Radio/CD
- Cloth seat trim
- Air conditioning


Photos







Condition Check




Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Door Mirror Assy nsf
Broken
Replace




3: Door nsf
Dented
With Paint Damage

4: Door nsf
Dented
Over 30mm



5: Qtr Panel nsr
Chipped
Multiple Chips

6: Qtr Panel Moulding ns
Scratched (Painted)
Over 25mm Thru Paint



7: Qtr Panel nsr
Hole
Over 10mm

8: Qtr Panel osr
Hole
Over 10mm



9: Qtr Panel Moulding os
Scratched (Painted)
Over 25mm Thru Paint

10: Qtr Panel osr
Chipped
Multiple Chips



11: Screen Front
Chipped
Over 10mm

12: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		