

VEHICLE INSPECTION REPORT

VN67KZS

Dennis Elite 6

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location	Avonmouth	GVW	26000kg	Cab Type	DAY CAB
Reg. date	19/12/2017	Colour	WHITE	Gearbox	AUTOMATIC
Year	2017	VIN	SEG2628HR6BH24299	Axle Combi	6x2
Mileage	159,308 Km Warranted	Body Style	Refuse Collector	Rear Suspension	Air
Fuel Type	DIESEL	MOT Due	Expired		

WARNING LIGHTS ON DASH, TACHOGRAPH REMOVED, REVERSING CAMERA INOP, OLYMPUS 21W BODY, TERBERG SPLIT LIFT


Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Digital radio
- Front electric windows
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Screen Front
Chipped
Over 10mm

2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Scratched
Over 100mm Thru Paint

4: Door Mirror Assy nsf
Broken
Replace



5: Door nsf
Scratched
UpTo 25mm Thru Paint

6: Door Moulding nsf
Broken
Replace



7: Door nsf
Chipped
Multiple Chips

8: Qtr Panel nsr
Rusted
Over 5mm



9: Qtr Panel Moulding ns
Broken
Replace

10: Qtr Panel Moulding ns
Broken
Replace



11: Qtr Panel Moulding os
Broken
Replace

12: Qtr Panel osr
Scratched
Rusted




13: Door osf
Chipped
Multiple Chips

14: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



15: Moulding osf Wing
Scratched (Painted)
UpTo 25mm Thru Paint

16: Seat Back Cover osf
Holed
Over 3mm



17: Seat Back Cover nsf
Holed
Over 3mm

18: Seat Base Cover nsf
Holed
Over 3mm



19: Steering Wheel
Damaged
Replace

20: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		