

VEHICLE INSPECTION REPORT

VN67KZT

Dennis Elite 6

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location	Avonmouth	GVW	26000kg	Cab Type	DAY CAB
Reg. date	20/12/2017	Colour	WHITE	Gearbox	AUTOMATIC
Year	2017	VIN	SEG2628HR6BH24300	Axle Combi	6x2
Mileage	117,773 Km Warranted	Body Style	Refuse Collector	Rear Suspension	Air
Fuel Type	DIESEL	MOT Due	31/01/2027		

TACHOGRAPH REMOVED, OLYMPUS 21W BODY, TERBERG SPLIT LIFT


Tyres









NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Radio/CD
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Fogdriving Lamp osf
Broken
Replace

2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Poor Previous Repair
Poor Colour

4: Wing nsf
Cracked
Replace




5: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

6: Door Moulding nsf
Broken
Replace



7: Wing Front Arch Extension ns
Broken
Replace

8: Qtr Panel nsr
Rusted
Over 5mm



9: Panel Rear
Poor Previous Repair
Poor Paint

10: Qtr Panel osr
Dented
Hail - Severe



11: Door osf
Scratched
Over 25mm Thru Paint

12: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



13: Moulding osf Wing
Broken
Replace

14: Seat Base Cover osf
Holed
Over 3mm



15: Seat Base Cover osf
Burn
Over 3mm

16: Centre Console Front
Broken
Replace



17: Fascia Panel
Missing
Replace

18: Seat Base Cover osf
Holed
Over 3mm



19: Fascia Trim
Missing
Replace

20: Fascia Trim
Missing
Replace



21: Fascia Trim
Missing
Replace

22: Seat Back Cover osf
Torn
Over 3mm



23: Door Pad osf
Broken
Replace

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	-
Engine Runs	OK		No Excessive Smoking	OK
EML light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK			