

VEHICLE INSPECTION REPORT

WS19AEV

Fiat Ducato 35 2.3 II MULTIJET 130PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Location	Doncaster	GVW	3500kg	CAP Clean	£3,750.00
Reg. date	06/08/2019	Colour	WHITE	CAP Average	£3,225.00
Year	2019	VIN	ZFA25000002L56008	CAP Below	£2,525.00
Mileage	140,643 Miles Warranted	Body Style	Panel Van MWB	Gearbox	MANUAL
Fuel Type	DIESEL	MOT Due	26/06/2027	Gears	6

SIDE LOAD DOOR, E/ MIRRORS, TOW BAR, DEADLOCKS, RACKING IN REAR

Tyres

NSF

NSR

OSF

OSR


Spare

Features

- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Rear parking sensor
- Drivers airbag
- Digital radio
- Passenger airbag
- Air conditioning
- Central locking


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Panel Front
Scratched
Over 25mm Thru Paint



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Door nsf
Dented
With Paint Damage




5: Door nsf
Chipped
Multiple Chips



6: Door Moulding nsf
Missing
Replace



7: Qtr Panel nsr
Dented
With Paint Damage



8: Qtr Panel nsr
Dented
Over 30mm






9: Qtr Panel nsr
Chipped
Multiple Chips

10: Qtr Panel nsr
Chipped
Multiple Chips



11: Door nsr
Dented
With Paint Damage

12: Door nsr
Dented
With Paint Damage



13: Door nsr
Dented
With Paint Damage

14: Qtr Panel osr
Scratched
Over 25mm Thru Paint



15: Qtr Panel osr
Chipped
Multiple Chips

16: Qtr Panel osr
Chipped
Multiple Chips



17: Seat Base Cover osf
Soiled
Heavy

18: Seat Base Cover nsf
Soiled
Heavy



19: Door Pad osf
Soiled
Heavy

20: Carpets Front
Holed
Over 3mm

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	Poor	Odour	No
Engine Runs	OK		
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK