

VEHICLE INSPECTION REPORT

KU12WGV

Fuso Canter 7C18

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location	Bedford	Colour	WHITE	Axle Combi	4x2
Reg. date	03/05/2012	VIN	TYAFEB71GRDX01370	Rear Suspension	Steel
Year	2012	Body Style	Mobile Workshop	Rear Doors	Barn </td
Mileage	194,969 Km Warranted	MOT Due	31/08/2026	Tail Lift	Cantilever
Fuel Type	DIESEL	Cab Type	DAY CAB		
GVW	7500kg	Gearbox	AUTOMATIC		


SEATING AREA, WORKSTATION, MICROWAVE, SOCKETS, TOILET

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


Photos







Condition Check



Damage Photos



1: Door osf
Rusted
Over 5mm

2: Door nsf
Rusted
UpTo 5mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour -

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK