

VEHICLE INSPECTION REPORT

FJ64RZV

Mercedes-Benz Atego 1324

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location	Bedford	GVW	13500kg	Cab Type	DAY CAB
Reg. date	17/10/2014	Colour	WHITE	Gearbox	MANUAL
Year	2014	VIN	WDB9670262L864618	Axle Combi	4x2
Mileage	77,146 Km Warranted	Body Style	Vacuum Tanker	Rear Suspension	Air
Fuel Type	DIESEL	MOT Due	30/11/2026		

PALFINGER PC1500 REMOTE EQUIPMENT (YEAR 2014)


Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Park assist camera
- Air conditioning


Photos







Condition Check



Damage Photos



1: Wing osf
Scratched
UpTo 25mm Thru Paint

2: Door osf
Rusted
UpTo 5mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour -

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK