

VEHICLE INSPECTION REPORT

LX65BCK

Mercedes-Benz Sprinter 513 CDI

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 28/01/2016

GVW 5000kg

MOT Due 27/01/2027

Year 2016

Colour WHITE

Gearbox AUTOMATIC

Mileage 158,620 Miles Not Warranted

VIN WDB9066552P217231

Tail Lift Tuckaway

Fuel Type DIESEL

Body Style Minibus

SIDE LOAD DOOR, 15 SEATS + DRIVER, LOLER INSPECTION REPORT PRESENT

Tyres

NSF

NSR

OSF



OSR





Spare

Features


- Park assist camera
- Rear parking sensor
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos




1: Bonnet
Chipped
Multiple Chips

2: Screen Front
Chipped
Over 10mm



3: Bumper Front
Dented
Between 10mm + 30mm

4: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



5: B Post ns
Rusted
Over 5mm

6: Door nsr
Dented
Between 10mm + 30mm



7: Qtr Panel Trim ns
Scuffed
Over 25mm

8: Door nsr
Dented
With Paint Damage



9: Door osr
Dented
Between 10mm + 30mm

10: Door osr
Chipped
1 To 5



11: Qtr Panel osr
Rusted
Over 5mm

12: Qtr Panel osr
Rusted
Over 5mm



13: Qtr Panel osr
Rusted
Over 5mm

14: B Post os
Rusted
Over 5mm



15: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm

16: Sill os
Rusted
Over 5mm

Interior

Carpet Condition		OK	Upholstery Condition		OK
Seat Condition		OK	Odour		No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	