

VEHICLE INSPECTION REPORT

BX59DKE

Daf LF 45.160

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location	Bedford	GVW	7500kg	Cab Type	DAY CAB
Reg. date	24/09/2009	Colour	WHITE	Gearbox	MANUAL
Year	2009	VIN	XLRAE45FF0L353691	Axle Combi	4x2
Mileage	230,638 Km Warranted	Body Style	MOBILE WORKSHOP	Rear Suspension	Steel
Fuel Type	DIESEL	MOT Due	31/12/2026	Rear Doors	Roller


KITCHENETTE, GARDNER DENVER HYDRAPAK, C/W GAS HOB & SINK

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


Photos







Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Not Thru Paint

2: Bumper Front
Rusted
Over 5mm



3: Bonnet
Chipped
Multiple Chips

4: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



5: Wing Front Arch Extension ns
Scuffed (Unpainted)
Over 100mm

6: Wing nsf
Scratched
Over 25mm Thru Paint



7: Qtr Panel nsr
Cracked
Replace

8: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



9: Qtr Panel osr
Scratched
Over 25mm Thru Paint

10: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



11: Door osf
Chipped
Edge Chip

12: Door osf
Scratched
UpTo 25mm Thru Paint



13: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm

14: Wing Front Arch Extension os
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK