

VEHICLE INSPECTION REPORT

BU69TPF

Daf LF 230

Non Runner
Inspection

Serious Damage?		Vehicle	
No		VAT	Plus VAT
		V5	To Follow

Details

Location	Bedford	GVW	18000kg	Gearbox	MANUAL
Reg. date	15/11/2019	Colour	WHITE	Axle Combi	4x2
Year	2019	VIN	XLRAEL3700L490890	Rear Suspension	Air
Mileage	488,353 Km Warranted	Body Style	Fridge Box	Rear Doors	Roller
Fuel Type	DIESEL	Cab Type	DAY CAB	Tail Lift	Tuckaway

NON RUNNER-STARTS BUT CUTS OUT IMMEDIATELY THERMOKING 1-1000R UNIT, STANDY PLUG, SINGLE SIDE BARN DOOR


Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Park assist camera
- Air conditioning

Photos






Type Approval No.		DAF ALF 230 FA		Serial Number
Manufacturer	Model	Year of Original Registration	15/11/19	Year of Manufacture
Function	RIGID R	Year of Original Registration	15/11/19	Year of Manufacture
(1) Description of Weights	(2) Weight	(3) Weight	(4) Design Weight	(5) Design Weight
As a vehicle	18000	18000	18000	2600
Gross Weight	18000	18000	18000	2600
Train Weight	18000	18000	18000	2600
Max. Train Weight	18000	18000	18000	2600
Axle Weights	7500	7500	11500	11500
Axle 1	7500	7500	11500	11500
Axle 2	7500	7500	11500	11500
Axle 3	7500	7500	11500	11500
Axle 4	7500	7500	11500	11500
REPLACEMENT				



Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Not Thru Paint



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Scratched
25 to 100mm Thru Paint

4: Bumper Front
Scratched
25 to 100mm Thru Paint



5: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

6: Wing Front Arch Extension ns
Scuffed (Unpainted)
Over 100mm



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

8: Qtr Panel nsr
Poor Previous Repair
Poor Paint



9: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

10: Qtr Panel osr
Scratched
Over 25mm Thru Paint





11: Door osf
Scratched
Over 25mm Not Thru Paint

12: Door osf
Chipped
Edge Chip



13: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm

14: Wing Front Arch Extension os
Scuffed (Unpainted)
Over 100mm





15: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs		Fault	