

VEHICLE INSPECTION REPORT

BC15ZCE

Iveco Daily 70-170

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location Livingston

GVW 7000kg

Service documents Printout

Reg. date 03/08/2015

Colour WHITE

MOT Due 31/08/2026

Year 2015

VIN ZCFC270C105039010

Gearbox MANUAL

Mileage 148,487 Km Warranted

Body Style Panel Van LWB

Fuel Type DIESEL

Service history Yes

GARDNER DENVER COMPRESSOR, CABLE WINCH, PENNY HYDRAULICS KJ150 SWING LIFT, SIDE LOAD DOOR


Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Radio/CD
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Carpets Front
Torn
Over 10mm



2: Bonnet
Dented
Over 30mm



3: Wing osf
Poor Previous Repair
Poor Paint

4: Wing Front Arch Extension os
Scuffed (Unpainted)
UpTo 100mm



5: Flasher Side Repeater os
Broken
Replace

6: Door osf
Dented
With Paint Damage



7: Qtr Panel osr
Dented
With Paint Damage

8: Tailgate
Dented
With Paint Damage



9: Qtr Panel nsr
Dented
Over 30mm

10: Door nsf
Dented
Over 30mm



11: Wing nsf
Dented
With Paint Damage

12: Bumper Front
Cracked
Over 25mm



13: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

14: Roof
Dented
With Paint Damage

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Turbo Boosting	OK		Gearbox Static Gear Selection (engine running)	OK	
Parking Brake	OK		No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	
Windows	OK		Radio	OK	
			Steering	OK	