

VEHICLE INSPECTION REPORT

BT15MWK

Iveco Daily 70-170

Inspection

Vehicle

VAT	Plus VAT
V5	Present

Details

Location	Livingston	GVW	7000kg	Service documents	Printout
Reg. date	01/06/2015	Colour	WHITE	MOT Due	31/10/2026
Year	2015	VIN	ZCFC270C405011282	Gearbox	MANUAL
Mileage	157,025 Km Warranted	Body Style	Panel Van XLWB		
Fuel Type	DIESEL	Service history	Yes		

PENNY HYDRAULICS 1MTR K JOINT SWING LIFT, COMPRESSOR GENERATOR, CABLE REEL, SIDE LOAD DOOR, TOW BAR

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Radio/CD
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Seat Base Cover of
Torn
Over 3mm



2: Bonnet
Dented
With Paint Damage



3: Door osf
Dented
With Paint Damage



4: Qtr Panel osr
Dented
Over 30mm



5: Tailgate
Dented
With Paint Damage

6: B Post ns
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK

Windows

OK

Radio

OK

Steering

OK