

VEHICLE INSPECTION REPORT

PJ70KRF

Mercedes-Benz Sprinter 314 CDI

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 18/01/2021

Year 2021

Mileage 178,468 Miles
Warranted

Fuel Type DIESEL

GVW 3500kg

Colour WHITE

VIN W1V9076332P282275

Body Style Panel Van L2

MOT Due 17/01/2027

CAP Clean £9,250.00

CAP Average £8,250.00

CAP Below £6,800.00

Gearbox MANUAL

Gears 6

AD-BLUE, SIDE LOAD DOOR, TOW BAR, TACHO 287223 KM, SERVICE SCHEDULE LIST AVAILABLE

Tyres

NSF

NSR

OSF


OSR





Spare

Features

- Bluetooth connection
- Drivers airbag
- Cruise control
- Passenger airbag
- Digital radio
- Cloth seat trim
- Front electric windows


Photos







Condition Check



Damage Photos



1: Bonnet
Dented
With Paint Damage

2: Wings
Dented
Over 30mm



3: Door nsf
Dented
Over 30mm

4: Qtr Panel nsr
Dented
Over 30mm



5: Qtr Panel nsr
Dented
Over 30mm

6: Qtr Panel nsr
Dented
With Paint Damage



7: Door nsr
Dented
Over 30mm

8: Door nsr
Dented
Over 30mm



9: Door osr
Dented
Over 30mm

10: Door osr
Dented
With Paint Damage



11: Door osr
Scratched
Over 25mm Thru Paint

12: Door osr
Dented
With Paint Damage



13: Qtr Panel osr
Dented
With Paint Damage

14: Qtr Panel osr
Dented
With Paint Damage



15: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm

16: Door osf
Dented
With Paint Damage



17: Door osf
Dented
Over 30mm

18: Door osf
Dented
Over 30mm



19: Door osf
Dented
With Paint Damage

20: Seat Base Cover osf
Torn
Over 3mm



21: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		