

VEHICLE INSPECTION REPORT

BU69TNZ

Daf LF 230

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date	01/11/2019	Colour	WHITE	Axle Combi	4x2
Year	2019	VIN	XLRAEL3700L490678	Rear Suspension	Steel
Mileage	379,217 Km Warranted	Body Style	Fridge Box	Rear Doors	Roller
Fuel Type	DIESEL	Cab Type	DAY CAB	Tail Lift	Tuckaway
GVW	18000kg	Gearbox	MANUAL		

WARNING LIGHTS ON DASH THERMOKING T-1000R UNIT, STANDY PLUG, SURROUND CAMERA SYSTEM, SINGLE SIDE BARN DOOR

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Park assist camera
- Air conditioning


Photos







Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Not Thru Paint



2: Bumper Front
Chipped
Multiple Chips



3: Screen Front
Chipped
UpTo 10mm

4: Bonnet
Chipped
Multiple Chips



5: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

6: Wing nsf
Chipped
1 To 5



7: Door nsf
Scratched
UpTo 25mm Not Thru Paint

8: Wing Front Arch Extension ns
Scuffed (Unpainted)
Over 100mm



9: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



10: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



11: Door osf
Scratched
Over 25mm Not Thru Paint



12: Door osf
Chipped
Edge Chip



13: Door osf
Scratched
Over 25mm Not Thru Paint



Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK