

VEHICLE INSPECTION REPORT

WS19AEW

Fiat Ducato 35 2.3 MULTIJET II 130PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 06/08/2019

Year 2019

Mileage 116,086 Miles
Warranted

Fuel Type DIESEL

GVW 3500kg

Colour WHITE

VIN ZFA25000002L55861

Body Style Panel Van MWB

MOT Due 16/09/2026

CAP Clean £4,325.00

CAP Average £3,725.00

CAP Below £2,900.00

Gearbox MANUAL

Gears 6

AD-BLUE, E/ MIRRORS

Tyres

NSF

NSR

OSF


OSR

Spare

Features

- Bluetooth connection
- Digital radio
- Passenger airbag
- Front parking sensor
- Air conditioning
- Central locking
- Park assist camera
- Front electric windows
- Cloth seat trim
- Rear parking sensor
- Drivers airbag


Photos







Condition Check



Damage Photos



1: Bonnet
Dented
With Paint Damage

2: Bonnet
Chipped
Multiple Chips



3: Door Mirror Assy nsf
Broken
Replace

4: Door nsf
Scratched
Over 25mm Thru Paint




5: Qtr Panel nsr
Dented
Over 30mm

6: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



7: Qtr Panel nsr
Dented
Over 30mm

8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Door nsr
Dented
Over 30mm

10: Qtr Panel osr
Dented
Over 30mm



11: Carpets Front
Holed
Over 3mm

12: Seat Base Cover osf
Holed
Over 3mm



13: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	Poor	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		