

VEHICLE INSPECTION REPORT

YC70BVU

Ford Transit 350 2.0 EcoBlue 130ps

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location Avonmouth

Reg. date 09/02/2021

Year 2021

Mileage 33,226 Miles
Warranted

Fuel Type DIESEL

GVW 3500kg

Colour WHITE

VIN WF0EXXTTREL75864

Body Style Panel Van L2

Service history Part

Service documents Printout

Last service date 16/04/2026

MOT Due 21/10/2026

CAP Clean £11,300.00

CAP Average £10,100.00

CAP Below £8,350.00

Gearbox MANUAL

Gears 6

DEADLOCKS (NO KEYS), AD BLUE, SIDE LOAD DOOR, TOW BAR, E/MIRRORS, HEATED WINDSCREEN

Tyres

NSF

NSR

OSF

OSR





Spare

Features

- Bluetooth connection
- Park assist camera
- Air conditioning
- Central locking
- Cruise control
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Front parking sensor
- Digital radio
- Drivers airbag
- Heated front seat
- USB/iPod interface
- Passenger airbag


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front
Scratched
Over 100mm Thru Paint




3: Wing nsf
Dented
Over 30mm

4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Door Mirror Assy nsf
Broken
Replace

6: Qtr Panel nsr
Dented
With Paint Damage



7: Qtr Panel nsr
Scratched
Rusted

8: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

10: Qtr Panel nsr
Scratched
Rusted



11: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

12: Qtr Panel nsr
Dented
Between 10mm + 30mm



13: Door nsr
Dented
Over 30mm

14: Door nsr
Dented
Over 30mm



15: Door nsr
Dented
Over 30mm



16: Door nsr
Scratched
Over 25mm Thru Paint



17: Door nsr
Dented
With Paint Damage



18: Lamp osr
Broken
Replace



19: Door osf
Chipped
Multiple Chips

20: Door Mirror Assy osf
Broken
Replace



21: Centre Console Front
 Scuffed
 Over 25mm

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		