

VEHICLE INSPECTION REPORT

BU69TRX

Daf LF 230

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Location	Doncaster	Colour	WHITE	Axle Combi	4x2
Reg. date	05/12/2019	VIN	XLRAEL3700L491244	Rear Suspension	Air
Year	2019	Body Style	Fridge Box	Rear Doors	Roller
Mileage	294,850 Km Warranted	MOT Due	28/02/2027	Tail Lift	Tuckaway
Fuel Type	DIESEL	Cab Type	DAY CAB		
GVW	18000kg	Gearbox	MANUAL		

THERMOKING T-1000R UNIT, STANDBY PLUG

Tyres





NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


Features

- Radio/CD
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Door osf
Dented
Over 30% Of Panel



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Bonnet
Chipped
Multiple Chips



4: Door nsf
Rusted
Over 5mm



5: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



6: Qtr Panel nsr
Dented
With Paint Damage



7: Qtr Panel osr
Scratched
Over 25mm Thru Paint

8: Qtr Panel osr
Scratched
Over 25mm Thru Paint



9: Qtr Panel osr
 Scratched
 Over 25mm Thru Paint

10: Door Pad osf
 Soiled
 Heavy



11: Seat Base Cover osf
 Torn
 Over 3mm

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		