

## VEHICLE INSPECTION REPORT

**LF16RSX**

### Ford Transit Custom 310 2.2 TDCi 100ps EConetic

#### Inspection

Serious Damage? No

#### Vehicle

|          |                      |
|----------|----------------------|
| VAT      | Plus VAT             |
| V5       | Present              |
| Cap Id   | 26574                |
| Cap Code | FOTU221S1EVDTM2<br>L |

#### Details

|           |                            |                   |                   |             |           |
|-----------|----------------------------|-------------------|-------------------|-------------|-----------|
| Location  | Doncaster                  | Colour            | WHITE             | CAP Clean   | £3,125.00 |
| Reg. date | 13/05/2016                 | VIN               | WF0YXXTTGYGR66874 | CAP Average | £2,575.00 |
| Year      | 2016                       | Body Style        | Panel Van L1      | CAP Below   | £1,850.00 |
| Mileage   | 110,899 Miles<br>Warranted | Service history   | Yes               | Gearbox     | MANUAL    |
| Fuel Type | DIESEL                     | Service documents | Printout          | Gears       | 6         |
| GVW       | 3100kg                     | MOT Due           | 24/11/2026        |             |           |

\*WARNING LIGHTS ON DASH\* TWIN SIDE LOAD DOOR

#### Tyres

NSF

NSR

OSF

OSR




Spare

## Features

- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Rear parking sensor
- Drivers airbag
- Auxiliary input socket
- Passenger airbag
- Digital radio
- Central locking


## Photos







## Condition Check



## Damage Photos



1: Bonnet  
Dented  
With Paint Damage

2: Bonnet  
Chipped  
Multiple Chips



3: Bumper Front Moulding  
Scuffed (Unpainted)  
Over 100mm

4: Wing nsf  
Dented  
With Paint Damage



5: Wing nsf  
Scratched  
Over 25mm Not Thru Paint

6: Door nsf  
Scratched  
Over 25mm Thru Paint



7: Qtr Panel nsr  
Dented  
With Paint Damage

8: Qtr Panel nsr  
Dented  
With Paint Damage



9: Door nsr  
Dented  
With Paint Damage



10: Door nsr  
Scratched  
Over 25mm Thru Paint



11: Qtr Panel osr  
Dented  
With Paint Damage



12: Sill os  
Dented  
With Paint Damage



13: Door osf  
Chipped  
Multiple Chips



14: Screen Front  
Chipped  
Over 10mm





15: Door Pad osf  
Soiled  
Heavy

16: Seat Base Cover osf  
Holed  
Over 3mm



17: Dash Warning Lights  
Displayed  
No Action

Interior

|                       |  |       |                       |  |      |
|-----------------------|--|-------|-----------------------|--|------|
| Carpet Condition      |  | OK    | Upholstery Condition  |  | Poor |
| Seat Condition        |  | Poor  | Odour                 |  | No   |
| Engine Runs           |  | OK    | No Excessive Smoking  |  | OK   |
| EML light illuminated |  | Fault | DPF light illuminated |  | OK   |
| ABS light illuminated |  | OK    |                       |  |      |