

VEHICLE INSPECTION REPORT

EF17XJW

Scania P 360

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location Doncaster

Reg. date 14/07/2017

Year 2017

Mileage 249,475 Km Not Warranted

Fuel Type DIESEL

GVW 32000kg

Colour GREEN

VIN YS2P8X40009217382

Body Style Cement Mixer

MOT Due 30/11/2026

Cab Type DAY CAB

Gearbox AUTOMATIC

Axle Combi 8x4

Rear Suspension Steel

LIEBHERR MIXER BODY

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2


OSO3


OSO4

Features

- Bluetooth connection
- Radio/CD
- Cloth seat trim
- Cruise control
- Air conditioning
- Navigation system
- Front electric windows
- Digital radio
- Central locking


Photos








Condition Check



Damage Photos



1: Door Mirror Assy osf
Broken
Replace



2: Panel Front
Scratched
Over 25mm Thru Paint



3: Bumper Front
Scratched
Over 100mm Thru Paint

4: Bonnet
Chipped
Multiple Chips



5: Bumper Front
Scratched
Over 100mm Thru Paint

6: Panel Front
Scratched
Over 25mm Thru Paint



7: Door nsf
Scratched
Over 25mm Thru Paint

8: Lamp nsr
Broken
Replace



9: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		