

VEHICLE INSPECTION REPORT

EG19AEG

Daf XF 530

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Location	Bedford	GVW	44000kg	Cab Type	SUPER SPACE CAB
Reg. date	14/06/2019	Colour	SILVER	Gearbox	AUTOMATIC
Year	2019	VIN	XLRTGH4300G260254	Axle Combi	6x2
Mileage	713,883 Km Not Warranted	Body Style	Tractor Unit	Steering Combi	Mid-Lift
Fuel Type	DIESEL	MOT Due	31/08/2026	Rear Suspension	Air

LIMP MODE - TRANSMISSION & ENGINE FAILURE SLIDING 5TH WHEEL, FRIDGE, MICROWAVE, SINGLE LINE PTO HYDRAULICS

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


Features

- Navigation system
- Air conditioning


Photos







Condition Check



Damage Photos



1: Wing of
Chipped
Multiple Chips



2: Bonnet
Chipped
Multiple Chips



3: Bonnet
Scratched
Over 25mm Thru Paint

4: Bumper Front
Chipped
Multiple Chips



5: Screen Front
Chipped
UpTo 10mm

6: Bumper Front
Dented
With Paint Damage



7: Fog Lamp Surround ns
Scratched (Painted)
Over 25mm Thru Paint

8: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



9: Wing nsf
Scratched
Over 25mm Not Thru Paint

10: Wing Front Arch Extension ns
Scratched (Painted)
Over 25mm Thru Paint



11: Door nsf
Scratched
Over 25mm Not Thru Paint

12: Qtr Panel Arch Extension ns
Broken
Replace



13: Qtr Panel Arch Extension os
Broken
Replace

14: Qtr Panel osr
Rusted
Over 5mm



15: Door Mirror Assy osf
Broken
Replace

16: Door osf
Chipped
Edge Chip

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK