

VEHICLE INSPECTION REPORT

BG72GYT

Mercedes-Benz Sprinter 315 CDI PROGRESSIVE

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 14/10/2022

Year 2022

Mileage 102,084 Miles Not Warranted

Fuel Type DIESEL

GVW 3500kg

Colour WHITE

VIN W1V9071352N216053

Body Style Dropside L3

MOT Due 13/10/2026

CAP Clean £10,400.00

CAP Average £9,475.00

CAP Below £7,950.00

Gearbox MANUAL

Gears 6

WARNING LIGHT ON DASH, CRACK IN WINDSCREEN AD BLUE

Tyres

NSF

NSR

OSF


OSR




Spare

Features


- Park assist camera
- Air conditioning
- Front electric windows

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Screen Front
Cracked
Replace



3: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm

4: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



5: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

6: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



7: Door osf
Chipped
Edge Chip

8: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	Fault	