

VEHICLE INSPECTION REPORT

DK62WYW

Mercedes-Benz Axor 1843

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Location	Avonmouth	GVW	28000kg	Cab Type	SLEEPER CAB
Reg. date	24/10/2012	Colour	WHITE	Gearbox	AUTOMATIC
Year	2012	VIN	WDF9440322B977560	Axle Combi	4x2
Mileage	655,744 Km Warranted	Body Style	Tractor Unit	Rear Suspension	Air
Fuel Type	DIESEL	MOT Due	30/09/2026		

WARNING LIGHT ON DASH, SLIDING 5TH WHEEL

Tyres




NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Cruise control
- Radio/CD Multichanger
- Electric sunroof
- Air conditioning
- Front electric windows
- Cloth seat trim


Photos







Condition Check




Damage Photos



1: Screen Front
Cracked
Replace

2: Bonnet
Chipped
Multiple Chips




3: Roof
Rusted
Over 5mm

4: Bumper Front
Cracked
Over 25mm



5: Moulding nsf Wing
Scratched (Painted)
Over 25mm Thru Paint

6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door nsf
Scratched
Over 25mm Thru Paint

8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Qtr Panel nsr
Cracked
Replace



10: Qtr Panel osr
Cracked
Replace



11: Qtr Panel osr
Rusted
Over 5mm



12: Qtr Panel osr
Scratched
Over 25mm Thru Paint



13: Door osf
Dented
With Paint Damage



14: Wing Front Arch Extension os
Broken
Replace



15: Aperture Seal of
Broken
Replace

16: Rear Panel Trim Int
Broken
Replace



17: Centre Console Front
Holed
Over 3mm

18: Switches And Controls
Missing
Replace



19: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
Brakes	OK		
Parking Brake	OK		
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		