

VEHICLE INSPECTION REPORT

BU69TNX

Daf LF 230

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Location	Avonmouth	GVW	18000kg	Cab Type	DAY CAB
Reg. date	08/11/2019	Colour	WHITE	Gearbox	Manual
Year	2019	VIN	XLRAEL3700L490735	Axle Combi	4x2
Mileage	TBC	Body Style	Fridge Box	Rear Doors	Roller
Fuel Type	DIESEL	MOT Due	30/11/2026	Tail Lift	Tuckaway

COLLECTED AS NON-RUNNER-LIMP MODE, WARNING LIGHTS ON DASH, THERMOKING T-1000R UNIT, STANDBY PLUG, SIDE LOAD DOOR


Tyres







NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


Features

- Cruise control
- Park assist camera
- Radio/CD
- USB/iPod interface
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim


Photos








Condition Check



Damage Photos



1: Screen Front
Cracked
Replace

2: Bonnet
Chipped
Multiple Chips




3: Bumper Front
Scratched
Over 100mm Thru Paint

4: Wing Front Arch Extension ns
Scratched (Painted)
Over 25mm Thru Paint



5: Wing nsf
Scratched
Over 25mm Thru Paint

6: Qtr Panel osr
Poor Previous Repair
Poor Paint




7: Qtr Panel osr
Scratched
Over 25mm Thru Paint

8: Door osf
Chipped
Multiple Chips



9: Door osf
Scratched
Over 25mm Thru Paint

10: Bumper Front
Cracked
Over 25mm



11: Seat Base Cover osf
Torn
Over 3mm

12: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Gearbox Static Gear Selection (engine running)	OK	
Parking Brake	OK		No Excessive Smoking	OK	
EML light illuminated	Fault		DPF light illuminated	Fault	
ABS light illuminated	OK				