

## VEHICLE INSPECTION REPORT

**MM71RWV**

### Ford Ranger Wildtrak 2.0 EcoBlue 213

#### Inspection

Serious Damage? No

#### Vehicle

VAT Plus VAT

V5 Buyer To Apply

#### Details

|           |                           |            |                   |             |            |
|-----------|---------------------------|------------|-------------------|-------------|------------|
| Reg. date | 19/01/2022                | Colour     | BLACK             | CAP Average | £13,300.00 |
| Year      | 2022                      | VIN        | 6FPPXXMJ2PMD50390 | CAP Below   | £11,150.00 |
| Mileage   | 55,543 Miles<br>Warranted | Body Style | Pickup Double Cab | Gearbox     | AUTOMATIC  |
| Fuel Type | DIESEL                    | MOT Due    | 05/11/2026        | Gears       | 1          |
| GVW       | 3270kg                    | CAP Clean  | £14,600.00        | Axle Combi  | 4x4        |

\*WARNING LIGHTS ON DASH\* AD BLUE, ROOF RACK, ALLOY WHEELS, E/MIRRORS, HEATED WINDSCREEN

#### Tyres

NSF

NSR

OSF

OSR







Spare

## Features

- Bluetooth connection
- Navigation system
- USB/iPod interface
- Drivers airbag
- Cruise control
- Park assist camera
- Air conditioning
- Passenger airbag
- Front parking sensor
- Rear parking sensor
- Front electric windows
- Central locking
- Heated front seat
- Digital radio
- Rear electric windows
- Leather seat trim


## Photos








## Condition Check




## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips

2: Bumper Front  
Chipped  
Multiple Chips



3: Door nsf  
Chipped  
Multiple Chips

4: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



5: Qtr Panel nsr  
Dented  
Over 2 UpTo 10mm

6: Tailgate  
Scratched  
UpTo 25mm Thru Paint



7: Tailgate  
Chipped  
Multiple Chips

8: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



9: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint

10: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



11: Door osf  
Chipped  
Multiple Chips

12: Door osf  
Scratched  
Over 25mm Thru Paint



13: Wing osf  
Scratched  
Over 25mm Thru Paint

14: Dash Warning Lights  
Displayed  
No Action

## Interior

| Carpet Condition      | Average | Upholstery Condition  | Average |
|-----------------------|---------|-----------------------|---------|
| Seat Condition        | Average | Odour                 | -       |
| Engine Runs           | OK      | No Excessive Smoking  | OK      |
| Brakes                | OK      |                       |         |
| Parking Brake         | OK      |                       |         |
| EML light illuminated | OK      | DPF light illuminated | OK      |
| ABS light illuminated | OK      |                       |         |