

VEHICLE INSPECTION REPORT

FP70WJO

DAF XF 480

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Location	Bedford	GVW	44000kg	Cab Type	SUPER SPACE CAB
Reg. date	17/01/2021	Colour	WHITE	Axle Combi	6x2
Year	2021	VIN	XLRTGH4300G332069	Steering Combi	Mid-Lift
Mileage	634,383 Km Not Warranted	Body Style	Tractor Unit	Rear Suspension	Air
Fuel Type	Diesel	MOT Due	28/02/2027		

WARNING LIGHTS ON DASH, POSSIBLE INPUT ERROR ON MOT SURROUND CAMERA SYSTEM

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Air conditioning


Photos







Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Not Thru Paint



2: Screen Front
Chipped
Over 10mm




3: Bumper Front
Chipped
Multiple Chips



4: Bumper Front
Scratched
Over 25mm Not Thru Paint



5: Wing nsf
Scratched
Over 25mm Not Thru Paint



6: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



7: Wing Front Arch Extension ns
Scratched (Painted)
Over 25mm Thru Paint

8: Qtr Panel osr
Cracked
Replace



9: Door osf
Chipped
Edge Chip

10: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	Fault		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	