

VEHICLE INSPECTION REPORT

FP70WJL

Daf XF 480

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Location	Bedford	GVW	44000kg	Cab Type	SUPER SPACE CAB
Reg. date	17/01/2021	Colour	WHITE	Gearbox	AUTOMATIC
Year	2021	VIN	XLRTGH4300G332681	Axle Combi	6x2
Mileage	582,792 Km Not Warranted	Body Style	Tractor Unit	Steering Combi	Mid-Lift
Fuel Type	Diesel	MOT Due	28/02/2027	Rear Suspension	Air

SURROUND CAMERA SYSTEM

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4




Features

- Navigation system
- Air conditioning


Photos







Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Not Thru Paint

2: Bonnet
Chipped
Multiple Chips



3: Screen Front
Chipped
UpTo 10mm



4: Bumper Front
Scratched
25 to 100mm Thru Paint



5: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



6: Wing Front Arch Extension ns
Broken
Replace



7: Wing Front Arch Extension ns
Scratched (Painted)
Over 25mm Thru Paint



8: Wing Front Arch Extension os
Broken
Replace



9: Qtr Panel osr
Rusted
Over 5mm

10: Door Mirror Assy osf
Broken
Replace



11: A Post os
Scratched
Over 25mm Not Thru Paint

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK