

VEHICLE INSPECTION REPORT

AK69UWS

Ford Transit Custom 320 2.0 EcoBlue 130ps Trend

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Location	Doncaster	GVW	3200kg	CAP Clean	£7,050.00
Reg. date	17/12/2019	Colour	WHITE	CAP Average	£6,075.00
Year	2019	VIN	WF0YXXTTGYKU83785	CAP Below	£4,750.00
Mileage	108,183 Miles Warranted	Body Style	Panel Van L2	Gearbox	AUTOMATIC
Fuel Type	DIESEL	MOT Due	22/09/2026	Gears	6

AD BLUE, SIDE LOAD DOOR, E/MIRRORS, HEATED WINDSCREEN

Tyres

NSF

NSR

OSF



OSR






Spare

Features

- Bluetooth connection
- Cruise control
- Front parking sensor
- Park assist camera
- Rear parking sensor
- Digital radio
- USB/iPod interface
- Air conditioning
- Front electric windows
- Drivers airbag
- Passenger airbag
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Bonnet
Scratched
Over 25mm Thru Paint

4: Bumper Front
Scratched
Over 100mm Thru Paint



5: Wing nsf
Chipped
1 To 5

6: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



7: Door nsf
Dented
Over 2 UpTo 10mm

8: Door nsf
Dented
2 Or Less UpTo 10mm



9: Aperture Seal nsf
Broken
Replace

10: Qtr Panel nsr
Dented
With Paint Damage



11: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

12: Qtr Panel nsr
Chipped
Multiple Chips



13: Bumper Rear
Scratched
Over 100mm Thru Paint

14: Bumper Rear
Hole
Over 25mm



15: Qtr Panel osr
Chipped
Multiple Chips



16: Qtr Panel osr
Dented
Hail - Moderate



17: Qtr Panel osr
Dented
Over 30mm



18: Door osf
Dented
Hail - Moderate



19: Door osf
Scratched
Over 25mm Thru Paint

20: Wing osf
Dented
Over 30mm



21: Seat Base Cover osf
Torn
Over 3mm



22: Centre Console Front
Holed
Over 3mm



23: Carpets Front
Torn
Over 10mm



24: Fascia Trim
Damaged
Replace



25: Centre Console Front
Holed
Over 3mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
Brakes	OK		
Parking Brake	OK		
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		