

VEHICLE INSPECTION REPORT

SG13WGY

Peugeot Bipper 1.3 HDi 75PS S

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location Livingston

Colour BLUE

CAP Below £350.00

Reg. date 27/03/2013

VIN VF3AAFHZ0D8375432

Gearbox MANUAL

Year 2013

Body Style Panel Van

Gears 5

Mileage 63,642 Miles
Warranted

MOT Due 31/03/2027

Rear Suspension Steel

Fuel Type DIESEL

CAP Clean £690.00

GVW 1750kg

CAP Average £520.00

SIDE LOAD DOOR

Tyres

NSF

NSR

OSF


OSR

Spare

Features


- Rear parking sensor

Photos





Condition Check



Damage Photos



1: Sill os
Rusted
Over 5mm



2: Bonnet
Dented
Over 2 UpTo 10mm



3: Wing osf
Rusted
Over 5mm

4: Door osf
Dented
With Paint Damage



5: Qtr Panel osr
Dented
2 Or Less UpTo 10mm

6: Tailgate
Dented
With Paint Damage



7: Door nsr
Scratched
UpTo 25mm Not Thru Paint

8: Door nsf
Dented
With Paint Damage



9: Wing nsf
Dented
With Paint Damage

Interior

Carpet Condition	-	Upholstery Condition	-
Seat Condition	-	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK