

VEHICLE INSPECTION REPORT

SG13WHP

Peugeot Bipper 1.3 HDi 75 S

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location Livingston

Reg. date 27/03/2013

Year 2013

Mileage 99,549 Miles
Warranted

Fuel Type DIESEL

GVW 1750kg

Colour BLUE

VIN VF3AAFHZ0D8375312

Body Style Panel Van SWB

MOT Due 02/12/2026

CAP Clean £560.00

CAP Average £440.00

CAP Below £300.00

Gearbox MANUAL

Gears 5

SIDE LOAD DOOR.

Tyres

NSF

NSR

OSF


OSR


Spare

Features


- Rear parking sensor
- Radio/CD

Photos






Condition Check



Damage Photos



1: Sill os
Rusted
Over 5mm

2: Bonnet
Dented
With Paint Damage



3: Wing osf
Rusted
Over 5mm

4: Door osf
Dented
Over 30mm



5: Qtr Panel osr
Dented
With Paint Damage

6: Tailgate
Dented
With Paint Damage



7: Qtr Panel nsr
Dented
With Paint Damage

8: Door nsr
Dented
2 Or Less UpTo 10mm



9: Door nsf
Dented
Over 2 UpTo 10mm

10: Wing nsf
Hole
Over 10mm

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		No	
Engine Runs		OK		Gearbox 1st and Reverse Test		OK	
Brakes		OK		Clutch Slip Test from Static		OK	
Turbo Boosting		OK		Gearbox Static Gear Selection (engine running)		OK	
Parking Brake		OK		No Excessive Smoking		OK	
EML light illuminated		OK		Oil warning light illuminated		OK	
Airbag light illuminated		OK		DPF light illuminated		OK	
ABS light illuminated		OK		Service indicator light illuminated		OK	
Windows		OK		Radio		OK	
				Steering		OK	