

VEHICLE INSPECTION REPORT

SG13OFM

Peugeot Bipper 1.3 HDi 75PS S

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location Livingston

Reg. date 22/03/2013

Year 2013

Mileage 66,762 Miles
Warranted

Fuel Type DIESEL

GVW 1750kg

Colour BLUE

VIN VF3AAFHZ0D8375304

Body Style Panel Van SWB

MOT Due 28/12/2026

CAP Clean £680.00

CAP Average £510.00

CAP Below £325.00

Gearbox MANUAL

Gears 5

SIDE LOAD DOOR

Tyres

NSF

NSR

OSF


OSR

Spare

Features


- Rear parking sensor

Photos





Condition Check



Damage Photos



1: Carpets Front
Torn
Over 10mm



2: Sill os
Rusted
Over 5mm



3: Bonnet
Dented
Over 30mm

4: Wing osf
Rusted
Over 5mm



5: Door osf
Dented
Over 30mm

6: Qtr Panel osr
Dented
Over 30mm



7: Tailgate
Dented
With Paint Damage

8: Door nsf
Rusted
Over 5mm



9: Wing nsf
Dented
With Paint Damage

10: Door nsr
Dented
With Paint Damage



11: Roof
Dented
With Paint Damage

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Turbo Boosting	OK		Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK		No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK

Windows

OK

Radio

OK

Steering

OK