

VEHICLE INSPECTION REPORT

SG13WHR

Peugeot Bipper 1.3 HDi 75PS S

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location Livingston

Reg. date 27/03/2013

Year 2013

Mileage 91,967 Miles
Warranted

Fuel Type DIESEL

GVW 1750kg

Colour BLUE

VIN VF3AAFHZ0D8375628

Body Style Panel Van

MOT Due 09/03/2027

CAP Clean £580.00

CAP Average £460.00

CAP Below £300.00

Gearbox MANUAL

Gears 5

Rear Suspension Steel

SIDE LOAD DOOR

Tyres

NSF

NSR

OSF


OSR


Spare

Features


- Rear parking sensor

Photos





Condition Check



Damage Photos



1: Seat Base Cover osf
Torn
Over 3mm



2: Sill os
Rusted
Over 5mm



3: Bonnet
Dented
Over 2 UpTo 10mm

4: Wing of
Rusted
Over 5mm



5: Door of
Dented
With Paint Damage

6: Tailgate
Poor Previous Repair
Poor Paint



7: Qtr Panel nr
Dented
With Paint Damage

8: Door nr
Scratched
UpTo 25mm Thru Paint



9: Door nsf
Dented
Over 30mm

10: Wing nsf
Rusted
Over 5mm

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		No	
Engine Runs	OK			Gearbox 1st and Reverse Test	OK		
Brakes	OK			Clutch Slip Test from Static	OK		
Turbo Boosting	OK			Gearbox Static Gear Selection (engine running)	OK		
Parking Brake	OK			No Excessive Smoking	OK		
EML light illuminated	OK			Oil warning light illuminated	OK		
Airbag light illuminated	OK			DPF light illuminated	OK		
ABS light illuminated	OK			Service indicator light illuminated	OK		
Windows	OK			Radio	OK		
				Steering	OK		