

VEHICLE INSPECTION REPORT

HV69WPT

Mercedes-Benz Atego 821

Inspection

Vehicle

VAT	Plus VAT
V5	Present

Details

Location	Avonmouth	Colour	SILVER	Axle Combi	4x2
Reg. date	23/10/2019	VIN	WDB96702220339952	Rear Suspension	Air
Year	2019	Body Style	Box Van	Rear Doors	Barn
Mileage	91,919 Km Warranted	MOT Due	28/02/2027	Tail Lift	Cantilever
Fuel Type	DIESEL	Cab Type	HIGH ROOF SLEEPER CAB		
GVW	7490kg	Gearbox	AUTOMATIC		

WARNING LIGHTS ON DASH SINGLE SIDE DOOR


Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Cruise control
- Radio/CD
- Electric sunroof
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Moulding nsf Wing
Missing
Replace



3: Door nsf
Scratched
Over 25mm Thru Paint

4: Wing Front Arch Extension ns
Scratched (Painted)
UpTo 25mm Thru Paint



5: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

6: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



7: Qtr Panel osr
Scratched
Over 25mm Thru Paint

8: Wing Front Arch Extension os
Scratched (Painted)
Over 25mm Thru Paint



9: Door osf
Chipped
Multiple Chips

10: Moulding osf Wing
Missing
Replace



11: Bumper Front
Scratched
Over 100mm Thru Paint

12: Dash Warning Lights
Displayed
No Action



13: Centre Console Front
Holed
Over 3mm

14: Centre Console Front
Holed
Over 3mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		