

VEHICLE INSPECTION REPORT

YJ69ZTV

Mercedes-Benz Actros 2543

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location	Avonmouth	Colour	SILVER	Axle Combi	6x2
Reg. date	29/10/2019	VIN	WDB96302120368996	Steering Combi	Rear-Lift Steer
Year	2019	Body Style	Box Van	Rear Suspension	Air
Mileage	171,395 Km Warranted	MOT Due	31/08/2026	Tail Lift	Cantilever
Fuel Type	DIESEL	Cab Type	GIGASPACE CAB		
GVW	26000kg	Gearbox	AUTOMATIC		


Tyres





NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4



Features

- Bluetooth connection
- Air conditioning
- Cloth seat trim
- Cruise control
- Front electric windows
- Digital radio
- Drivers airbag
- Electric sunroof
- Central locking


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Badgedecal Front
Missing
Replace




3: Moulding nsf Wing
Scratched (Painted)
Over 25mm Thru Paint

4: Bumper Front Moulding
Missing
Replace



5: Bumper Front
Scratched
Over 100mm Thru Paint

6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door nsf
Chipped
Multiple Chips

8: Qtr Panel osr
Scratched
Over 25mm Thru Paint



9: Door osf
Chipped
Multiple Chips

10: Bumper Front Moulding
Missing
Replace



11: Bumper Front
Scratched
Over 100mm Thru Paint

12: Moulding osf Wing
Scratched (Painted)
Over 25mm Thru Paint

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	-
Engine Runs	OK		No Excessive Smoking	OK
Brakes	OK			
Parking Brake	OK			
EML light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK			