

VEHICLE INSPECTION REPORT

LN72UTS

Mercedes-Benz Sprinter 315 CDI PROGRESSIVE

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location	Bedford	Colour	SILVER	CAP Below	£16,500.00
Reg. date	05/10/2022	VIN	W1V9071352N212325	Gearbox	MANUAL
Year	2022	Body Style	Luton L3	Gears	6
Mileage	38,791 Miles Warranted	MOT Due	04/10/2026	Tail Lift	Column
Fuel Type	DIESEL	CAP Clean	£21,550.00		
GVW	3500kg	CAP Average	£19,650.00		

AD BLUE

Tyres

NSF

NSR

OSF


OSR

Spare

Features


- Front electric windows

Photos





Condition Check



Damage Photos



1: Wing of
Scratched
Over 25mm Thru Paint



2: Bumper Front Moulding
Scuffed (Unpainted)
Up To 100mm



3: Bumper Front
Dented
Over 30mm

4: Wing nsf
Dented
Over 30mm



5: Door Mirror Assy nsf
Broken
Replace

6: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



7: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

8: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm




9: Wing osf
Dented
Between 10mm + 30mm

10: Wing osf
Scratched
Over 25mm Thru Paint



11: Door osf
Dented
With Paint Damage

12: Door osf
Scratched
UpTo 25mm Thru Paint



13: Door osf
Chipped
Edge Chip

14: Seat Base Cover nsf
Burn
Over 3mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK