

VEHICLE INSPECTION REPORT

NA25VFU

Mercedes-Benz Sprinter 315 CDI

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Location	Doncaster	Fuel Type	DIESEL	Body Style	Curtainside
Reg. date	30/06/2025	GVW	3500kg	Gearbox	AUTOMATIC
Year	2025	Colour	WHITE	Gears	6
Mileage	39,530 Miles Not Warranted	VIN	W1V3H3FZ0SN330619	Tail Lift	Column

WARNING LIGHTS ON DASH AD-BLUE, E/ MIRRORS

Tyres

NSF

NSR

OSF


OSR



Spare

Features


- Bluetooth connection
- Drivers airbag
- Cruise control
- Passenger airbag
- Digital radio
- Central locking
- Front electric windows
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Thru Paint

2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Cracked
Over 25mm

4: Door Mirror Assy nsf
Broken
Replace



5: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault