

VEHICLE INSPECTION REPORT

HX73YPE

Mercedes-Benz Atego 816

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location	Doncaster	Colour	WHITE	Cab Type	DAY CAB
Reg. date	19/10/2023	VIN	W1T96700320676851	Gearbox	AUTOMATIC
Year	2023	Body Style	Pole Erection Unit	Axle Combi	4x2
Mileage	24,677 Km Warranted	Service history	Yes	Rear Suspension	Steel
Fuel Type	DIESEL	Service documents	Printout		
GVW	7490kg	MOT Due	31/10/2026		

WARNING LIGHT ON DASH, PALFINGER PK 5.01 SLD 5 REMOTE CRANE (YEAR 2023) 2 EXTENSION


Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4



Features

- Bluetooth connection
- Cruise control
- Park assist camera
- Radio/CD Multichanger
- Manual sunroof
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



3: Wing Front Arch Extension ns
Scratched (Painted)
Over 25mm Thru Paint

4: Door of
Chipped
Multiple Chips



5: Wing Front Arch Extension of
Scratched (Painted)
Over 25mm Thru Paint

6: Moulding of Wing
Scratched (Painted)
Over 25mm Thru Paint



7: Bumper Front
Scratched
Over 100mm Thru Paint

8: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
Brakes	OK		
Parking Brake	OK		
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault