

VEHICLE INSPECTION REPORT

HX73YSD

Mercedes-Benz Atego 816

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location	Bedford	GVW	7490kg	Cab Type	DAY CAB
Reg. date	26/02/2024	Colour	WHITE	Gearbox	AUTOMATIC
Year	2024	VIN	W1T96700720674889	Axle Combi	4x2
Mileage	21,780 Km Warranted	Body Style	POLE CARRYING UNIT	Rear Suspension	Steel
Fuel Type	DIESEL	MOT Due	28/02/2027		

WARNING LIGHT ON DASH HIAB X-HIDUO 062 REMOTE CRANE (YEAR 2023), SURROUND CAMERA SYSTEM

Tyres





NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Park assist camera
- Air conditioning
- Front electric windows


Photos







Condition Check



Damage Photos



1: Wing of
Scratched
Up To 25mm Not Thru Paint



2: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



3: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

4: Wing Front Arch Extension ns
Scuffed (Unpainted)
Over 100mm



5: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm

6: Wing Front Arch Extension os
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault