

## VEHICLE INSPECTION REPORT

**OY18LPN**

### Daf CF 450

#### Inspection

Serious Damage? No

#### Vehicle

VAT Plus VAT

V5 Buyer To Apply

#### Details

Reg. date 12/06/2018

Year 2018

Mileage 317,044 Km Not Warranted

Fuel Type DIESEL

GVW 32000kg

Colour BLUE

VIN XLRADM4100G187383

Body Style Tipper

MOT Due Expired

Cab Type DAY CAB

Gearbox AUTOMATIC

Axle Combi 8x4

Rear Suspension Steel

\*WARNING LIGHTS ON DASH\*, THOMPSONS STEEL BODY, HYVA TIPPING GEAR, SHEETING SYSTEM, WEIGH SYSTEM, MID-STEER

#### Tyres


| NSF   | NSI1 | NSI2 | NSI3 | NSI4 |
|-------|------|------|------|------|
| OSF   | OSI1 | OSI2 | OSI3 | OSI4 |
| Spare | NSO1 | NSO2 | NSO3 | NSO4 |
|       | OSO1 | OSO2 | OSO3 | OSO4 |


### Features

- Bluetooth connection
- Manual sunroof
- Central locking
- Cruise control
- Air conditioning
- Cloth seat trim
- Radio/CD
- Front electric windows
- Leather seat trim
- USB/iPod interface
- Drivers airbag


### Photos







## Condition Check



## Damage Photos




1: Screen Front  
Cracked  
Replace

2: Bonnet  
Chipped  
Multiple Chips



3: Bumper Front  
Dented  
With Paint Damage

4: Bumper Front Grill  
Broken  
Replace




5: Roof  
Cracked  
Replace

6: Bumper Front  
Scratched  
Over 100mm Thru Paint



7: Moulding nsf Wing  
Scratched (Painted)  
Over 25mm Thru Paint

8: Wing nsf  
Cracked  
Replace



9: Door Mirror Assy nsf  
Scratched (Painted)  
Over 25mm Thru Paint

10: Door nsf  
Scratched  
Over 25mm Thru Paint




11: Wing Front Arch Extension ns  
Scratched (Painted)  
Over 25mm Thru Paint

12: Qtr Panel nsr  
Scratched  
Rusted



13: Qtr Panel osr  
Chipped  
Multiple Chips

14: Door osf  
Chipped  
Multiple Chips



15: Wing Front Arch Extension os  
Scratched (Painted)  
Over 25mm Thru Paint

16: Moulding osf Wing  
Broken  
Replace



17: Bumper Front  
Scratched  
Over 100mm Thru Paint

18: Door Mirror Assy osf  
Scratched (Painted)  
Over 25mm Thru Paint



19: Door Pad osf  
Broken  
Replace

20: General Interior  
Soiled  
Light



21: Fascia Panel  
Broken  
Replace

22: Fascia Trim  
Missing  
Replace



23: Centre Console Front  
Holed  
Over 3mm

24: Dash Warning Lights  
Displayed  
No Action

## Interior

| Carpet Condition      | Average | Upholstery Condition  | Average |
|-----------------------|---------|-----------------------|---------|
| Seat Condition        | Average | Odour                 | -       |
| Engine Runs           | OK      | No Excessive Smoking  | OK      |
| Brakes                | OK      |                       |         |
| Parking Brake         | OK      |                       |         |
| EML light illuminated | Fault   | DPF light illuminated | OK      |
| ABS light illuminated | OK      |                       |         |